

SET OF (2) OUTRIGGERS


Item # APOR




INCLUDED HARDWARE



8X 5/16-18 X 1" CSK SOCKET HEAD SCREW



20X 5/16-18 X 1.75" L CSK SOCKET HEAD SCREW





TOOLS REQUIRED



BUBBLE LEVEL



TAPE MEASURE



1/4" WALL ANCHORS (STYLE DEPENDENT ON WALL STRUCTURE)



POWER DRILL




STEP LADDER




2 PEOPLE REQUIRED FOR ASSEMBLY


Item # APOR SHEET 1 OF 4



4A



4B




WITH AT LEAST 2 PEOPLE, POSITION THE ASSEMBLED UPRIGHT AGAINST THE WALL.

USING A LEVEL, CHECK THAT THE POST IS PLUMB.

MARK AND SECURE THE WALL MOUNTING BRACKETS TO THE WALL AS REQUIRED WITH APPROPRIATE HARDWARE.

BE SURE THE LEVELER IS FIRMLY CONTACTING THE FLOOR. IF NOT, UNTHREAD UNTIL IT IS.




6

SECURE REMAINING OUTRIGGERS WHERE THEY ARE REQUIRED.

FOLLOW THE PRIOR STEPS TO ASSEMBLE REMAINING OUTRIGGER.

NOTE: THE OUTRIGGERS WILL BE PLACED SO THAT THE FRONT MEASURE 24" OR 48" OUTSIDE-TO-OUTSIDE.



RECOMMENDED BUT NOT MANDATORY

IT IS RECOMMENDED TO LOOSELY SECURE THE NEXT POST TO THE WALL SO AN ACCESSORY CAN BE TESTED.

IF THE ACCESSORY IS DIFFICULT TO INSTALL OR REMOVE, THE UPRIGHT WILL NEED TO BE ADJUSTED.

IF THE ACCESSORY IS NOT LEVEL, THE UPRIGHT LEVELERS MAY NEED TO BE ADJUSTED.

IF ACCESSORIES ARE NOT AVAILABLE, USE A TAPE MEASURE TO CHECK THE DISTANCE ON THE FRONT (SEE ABOVE.)

